## **Conservation Area 8 : Trowse Millgate**

\* Buildings added 19 March 2008

\*Former Pineapple Public House Mid C19. White brick with quoin and string course detailing. Slate. Timber sash windows. Ornate corner 'shopfront' includes 'pineapple' motifs

in the detailing of the capitals.

Importance: Good example of a Victorian public house located here because of the railway.

\*Railway Station and curtilage Buildings

1844. Mostly single storey with low two storey central gable. Flint with slate roof. Gables have shaped timber bargeboard detailing. Timber sash windows (central section has cruciform timber

windows). Five white brick stacks.

Importance: Early example of railway station

\*The Railway Bridge

Mid C19. Blue and red brick. Importance: a significant piece of mid C19th

railway infrastructure, the railway arches in particular are an unusual feature in Norfolk.

Trowse Pumping Station (two buildings)

1909. Industrial buildings.

a) At rear: 3 storeys red brick. Slate roof. Arched door and windows. Moulded brick cornice.
Entrance at 2nd storey level at top of steps.
b) At front: 2 storeys red brick. Tiled roof. 3 gables, central gable with clock. 2nd storey

windows semi-circular. Moulded decorative

brickwork.

1-6 (inc.) Trowse Pumping Station Cottages Early C20. 2 storeys terrace red brick with white brick window dressings and doorway surrounds. Slate and pantile roof. 1 sash each. Some arched windows and doorways. 2 gables at centre of terrace.

\*The White House

Early to mid C20. Two storey double fronted with overhanging eaves. Concrete blockwork whitewashed and roughly hewn quoin detailing. Blue plain tiled roof. Two red brick stacks. Metal windows retain red tile detailing above ground floor windows.

Importance: Early example of concrete

housing.

\*The River Bridge C15? Rebuilt 1863. Widened 1886. Flood

damaged and repaired 1912. Red brick with stone

facing and iron railings. South span includes

medieval groins.

Importance: Good example of C19 bridge

incorporating surviving medieval fabric.

\*Heron Island House 1970's. Fair faced concrete blockwork. Dark

stained timber windows.

Importance: An unusual style of house by local

architect Malcolm Rose.

Trowse House 1884. 2 storeys, red brick. Hipped slate roof. Cottages

Central gable. 3 entrance doorways with semi-

circular lights. Sashes.

C.19 2 storeys, red brick. Hipped pantile roof. Mill House Cottage

Shallow arched sashes. Central entrance with

decorative brick architrave.